

NSJ EnviroSciences Pty Ltd t/a MouldLab

ABN 27 143 789 995

PO Box 306 WICKHAM NSW 2293

Phone: 02 4968 8448 Fax: 02 8004 3576 Mobile: 0410 239 848 Email:

ANALYTICAL REPORT

CLIENT: Airconstruct HVAC Pty Ltd

37 Carlyle Street Mackay QLD 4740

PROPERTY: Withheld

PURPOSE OF THIS REPORT: To detect mould and bacteria present and

determine mould and bacterial counts and predominant mould genera in the samples taken from within the premises pre

remediation.

DATE OF SAMPLING: Withheld

SAMPLED BY: Withheld

DATE SAMPLE/S RECEIVED: Withheld

DATE OF REPORT: Withheld

PREPARED BY: Withheld

REPORTED AND Withheld RELEASED BY: Withheld

OUR REFERENCE: Withheld

AIHA Environmental Microbiology Proficiency Program EMPAT Participant Lab. No:



ANALYTICAL REPORT

1 INSTRUCTIONS

- 1.1 Samples collected at the property were submitted by Airconstruct HVAC Pty Ltd.
- 1.2 The purpose of the samples submitted for analysis was to detect and report on mould and bacteria present.

2 COMMENTARY

- 2.1 The samples collected were referred under chain of custody to our laboratory for analysis and reporting.
- 2.2 The samples received were labelled and in an intact condition.
- 2.3 This is an Analytical Report only and may not be in a format acceptable for litigation purposes because different Jurisdictions have differing requirements. Please contact MouldLab for further assistance.
- 2.4 Unless MouldLab has either performed the assessment from which these samples emanate or has been provided with the requisite certification from the sampler as per Reference 8, the results contained in this report should not be relied upon as the sole criteria for granting "clearance" or post remediation verification by any party.
- 2.5 In accordance with our Terms & Conditions this document and its contents are intended for the Addressee only and contains opinions held by the Author who prepared this report based on material available at the time of preparation and expressed for the purposes of consideration by the Addressee and is not for general publication without written consent.
- 2.6 Copyright of this report is retained by the Author and the Addressee is granted an exclusive licence to its contents and use only when payment for this report is received in full, in accordance with Clause 10 of MouldLab's Terms & Conditions.
- 2.7 Extraction or copying of this document, except in full, without the written consent of MouldLab is unauthorised.



3 RESULTS

3.1 **BIOTAPE SURFACE LIFTOFFS**

The results of the surface mould detected in the samples collected from the property were tabulated as follows:

	Saraji Mine Dysart QLD 4745 Our Ref: 131724	Mould/cm^2	Slide Area Counted %	Fungal Hyphae	Un-Id Fungal Spores	Pollen	Gen Dirt & debris	Acremonium spp.	Alternaria spp.	Ascomycetes	Aspergillus/Penicillium	Basidospores	Bipolaris/Dreschlera	Chaetomium spp.	Cladosporium spp.	Curvularia spp.	Epicoccum spp.	Fusarium spp.	Ulocladium spp.	Stemphylium spp.	Trichoderma spp.	Stachybotryis spp.	Zygomycetes	Torula spp.
1	Evaporator Left Side	>61496	5	>5000	-	_	VVVH	-						_	>5000									
2	Evaporator Right Side	>56510	5	>5000	>100	-	VVVH							>100	>5000									
	Lower limit of detection = BDL 1 mould/cm2 @ 50%	<5	0	<50	500 - 10 1000 5						>50	00	Elevated Further investigation is warranted when mould spores + hyphae were detected on surfaces at concentrations greater than 500/cm ² .											
		Low		Normal Mould Ecology		Elevated		High					High											
	Rating										Very High		Where the total surface spore and hyphal concentration was above 1000/cm² active mould may have been present or cross contamination may have ocurred. The cause and source of the mould should be determined and redressed.									n		
								_					Very High											
													When the surface mould spore & hyphal concentrations exceed 5,000/cm ² active mould was present on these surfaces and remediation to remove the mould growth is required.											

The above results are discussed in the conclusions.

3.2 SURFACE (SWAB) MOULD AND BACTERIA

The result of the surface mould and bacteria detected in the sample collected from the property was tabulated as follows:

ა Sample	Evaporator - LHS	Bacteriacfu/plate	Acremonium spp.	Alternariaspp.	Aspergillus spp.	Aspergillus niger	Aureobasidium spp.	Bipolaris/Dreschlera	Chaetomium spp.	Cladosporium spp.	Curvularia spp.	Fusarium spp.	Epicoccum spp.	Paecilomycesspp.	Penicillium spp.	Pithomyces spp.	Stemphyliumspp.	Trichodermaspp.	Stachybotrys spp.	Zygomycetes	Yeasts	Mould cfu/plate
3 Evaporator - LHS >100 >500 >100 >100 >500 >100												>2300										
	Rating	<5	<50		50 - 100		100 - 250		>250		Elevated Further investigation is warranted when viable mould were detected on											
		}	Ś							surfaces at concentrations between 50-100 cfu/plate or more than 25 cfu/plate if potentially pathogenic genera (in red) were detected.												
		3	Š						_	High												
		Normal Mould Ecology		Elevated		High		Very High		Above 100 cfu/plate active mould contamination may have been present on the surface. The cause and source of the mould should be determined and redressed.												
										Very High												
										If surfaction of the surfactio	inatio	n was	s pres	sent c	n the	se su	rfaces	and		, ,		d ove the

The above result is discussed in the conclusions.



4 CONCLUSIONS

- 4.1 The levels of surface mould detected in the samples collected from within the premises were rated as **Very High** on microscopy.
- 4.2 The level of surface mould (swab) detected in the sample collected from within the premises was rated as **Very High** on culture.
- 4.3 Very high levels of fungal hyphae were detected the presence of fungal hyphae is indicative of active mould growth and therefore constitutes a potential health hazard.
- 4.4 A high level of bacteria was detected in sample 3 submitted for analysis.
- 4.5 With reference to the types and levels of mould detected in the samples submitted from the above site, genera of mould were detected which include species which are known^{1,7} to be either:
 - Immunocompromising; and/or
 - Allergenic; and/or
 - Mycotoxin producers.
- 4.6 Additional assessment is recommended to determine the scope of the mould contamination and mould amplification within the premises.
- 4.7 Therefore, on the basis of the results from the samples provided, both the HVAC System and the premises require remediation by an accredited remediator, employing methods as set out in the HVAC Hygiene Guidelines⁶ and the ANSI Standard s520 (2008), published by the IICRC² or equivalent.
- 4.8 Following remediation, retesting of the premises to confirm post remediation validation should be performed.

For and on behalf of NSJ EnviroSciences Pty Ltd ABN 27 143 789 995 t/a MouldLab

DAVID LARK Mycologist



REFERENCES:

- 1. "Microorganisms in home and indoor work environments. Diversity, health impacts, investigation & control." Flannigan, B, Samson, R. A & Miller, J. D. 2nd Edn. 2011. CRC Press, Boco Raton, London & New York.
- 2. "Standard & Reference Guide for Professional Mold Remediation" IICRC s520 Aug. 2008, 2nd Ed. Institute of Inspection, Cleaning & Restoration Certification, Vancouver, Washington 98661 USA.
- "WHO Guidelines for Indoor Air Quality Dampness and Mould", 2009
 World Health Organisation, Copenhagen, Denmark,
 ISBN 978 92 890 4168 3.
- **4.** "Australian Mould Guideline (AMG 2010)". Kemp, P.C et al. 2nd Edn. 2010 Messenger Publishing.
- "Worldwide Exposure Standards for Mold & Bacteria Assessment Guidelines for Air, Water, Dust Ductwork, Carpet & Insulation", 8th Ed., 2010 Robert C. & Gail M. Brandys, OEHCS, Inc. IL. ISBN 0-9774785-0-5
- **6.** "HVAC Hygiene Guidelines, 2009" Australian Institute of Refrigeration, Air Conditioning & Heating.
- **7.** "Food & Indoor Fungi" Samson, R.A et al CBS-KNAW Fungal Biodiversity Centre, Utrecht, The Netherlands ISBN 978 90 70351 82 3.
- **8.** "Post-Remediation Testing and Verification for Mold and Bacteria" 4th Ed., 2011-Robert C. & Gail M. Brandys, OEHCS, Inc. IL. ISBN 978-0-9774785-1-4.